



INSTRUCTION SHEET

BL - SO


MOUNT SLICK-ON (SO) TO RIGID OR SWIVELING 3/4" CONDUIT

1. Thread SO hanger onto conduit.
2. Orient SO so that the body is parallel (II) or perpendicular (I) to room walls.
3. Tighten set screw to secure hanger.
4. Pull supply wires and ground. Extend them 4-6" below hanger opening.
5. Store SO hanger covers across the turned in ledges. Tape in place, if necessary.



MOUNT SLICK-ON (SO) TO CEILING OR JUNCTION BOX

1. Attach SO hanger to 3 1/2" dia. B.C., rigidly mounted, J-Box with 4 screws (not furnished), or place SO hanger against suitable mounting surface and use the four (4) KO holes in top as a template to drill the mounting holes.
2. Orient SO hanger so that the body is parallel (II) or perpendicular (I) to room walls.
3. Fasten SO hanger to drilled ceiling structure using suitable hardware such as lag bolts, expanding bolts or threaded screws (not furnished).
4. For through wire applications, attach conduit to KO holes in side of SO hanger. Use locknuts and bushings (not furnished) to secure the conduit in place.
5. Pull supply wires and ground. Extend a short feeder wire section 4-6" below hanger opening.
6. Store SO hanger covers across the turned in ledges of the hanger. Tape in place, if necessary.



268-0651-9901



Hubbell Lighting, Inc.
 A Subsidiary of Hubbell Incorporated
 2000 Electric Way
 Christiansburg, VA 24073-2500
 (703) 382-6111
 FAX (703) 382-1526

ORIGINAL DRAWING